

Temat: Skoroszyce, ul. Braterstwa Broni									
nr otworu:		S2		nr sondowania:		SL2			
WYKRES SONDOWANIA SONDĄ LEKKĄ SL (DPL)									
	luźny	średnio zagęszczony	zagęszczony	bardzo zagęszczony	głębokość [m p.p.t.]	litologia	\overline{N}_{10}	I_D	I_s
0,2-0,1					0,0-0,5	gleba	5		
0,4-0,3									
0,5-0,6									
0,7-0,8									
0,9-1,0									
1,1-1,2									
1,3-1,4									
1,5-1,6									
1,7-1,8									
1,9-2,0									
2,1-2,2					0,5-3,9	Gp+KO	21	0,64	
2,3-2,4									
2,5-2,6									
2,7-2,8									
2,9-3,0									
3,1-3,2									
3,3-3,4									
3,5-3,6									
3,7-3,8									
3,9-4,0									
4,1-4,2									
4,3-4,4									
4,5-4,6									
4,7-4,8									
4,9-5,0									
5,1-5,2									
5,3-5,4									
5,5-5,6									
5,7-5,8									
5,9-6,0									
6,1-6,2									
6,3-6,4									
6,5-6,6									
6,7-6,8									
6,9-7,0									
7,1-7,2									
7,3-7,4									
7,5-7,6									
7,7-7,8									
7,9-8,0									
8,1-8,2									
8,3-8,4									
8,5-8,6									
8,7-8,8									
8,9-9,0									
					Zał. 7.2.				